

Original Customer Requests	Status	Cost	Declined	Approved
3. DRIVERS SIDE RUNNING LIGHT ON FRONT NEEDS TO BE CHANGED		\$0.00	X	
4. DRIVERS SIDE HEADLIGHT TILTED DOWN. BRACKET BROKEN PLEASE REPAIR		\$0.00	X	
replace driver xenon headlight assy (headlight adjustment bracket broken)		\$676.53	X	
1. CUST STATES VEHICLE FEELS LIKE IT STALLING OUT CHE CK AND ADVISE TRANS. LURCHING BETWEEN 1-2 SEEMS TO DO IT MORE WHEN WARMED UP. HAS NOTICED TRANS. FLUID ON THE GROUND RECENTLY		\$110.00		X
replace auto transmission (transmission poorly shifting)		\$7,743.02	X	
Inspection Recommendations	Status	Cost	Declined	Approved
Perform AC system refresh service (Found cabin/HEPA micro filter dirty)	Fail	\$79.95	X	
Replace cabin/HEPA micro filter (Found cabin/HEPA micro filter dirty)	Fail	\$73.13	X	See AI-18
Replace left headlight bulb (Found driving lights to be burned out)	Fail	\$273.47	X	See AI-41
Replace spark plugs (Found spark plugs in poor condition)	Fail	\$186.20	X	See AI-50
Replace valve cover gasket (Found engine oil leak)	Fail	\$308.09	X	See AI-103
Mount and balance 2 new rear tires (Found rear tires abnormally worn)	Caution	\$771.88	X	See AI-23
Totals, Taxes and Fees		Cost	Declined	Approved
Estimate Subtotal		\$10,222.2	\$10,112.27	\$110.00
Shop Supplies		\$34.33		\$8.80
Tax 8.00%		\$820.53		\$9.50
<b>Estimate Total</b>		<b>\$11,077.1</b>		<b>\$128.30</b>
<i>For "See AI-" items <span style="background-color: #a67c52; color: white; padding: 2px;">    </span> see the "Additional Info</i>				



## Additional Information

Below is information we feel would help you better understand some of the reasons for taking preventive maintenance steps – steps that help to ensure the reliability and safety of your vehicle for you and your family.

\*\* The following section may contain instructions for servicing various components of your vehicle. These are an overview of the process that will be performed by a skilled technician in our shop. They are not intended to