

JOB# 1 CHARGES

LABOR-----
 J# 1 23BFZ MANUAL TRANS UNITS: 6.83 TECH(S):153 WARRANTY
 COMPLAINT: CHECK FLYWHEEL BEEN REPLACED AT MINI RICHMOND
 MAKING NOISE IN FIRST AND REVERSE
 CORRECTION: CHECK FOR NOISE ON TAKE OFF-ROAD TEST-TRACE TO FLYWHEEL-REPL
 ACE FLYWHEEL WITH NEW-REASSEMBLE-ROAD TEST OK-PARTS WARRANTY
 -REPLACED 02-07-07 AT RICHMOND-RO-202151-CLAIM #18253

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
	17	83-22-0-390-332	MTF94 GEAR OIL		WARRANTY
	1	07-13-6-801-196	SELF-LOCKING HEX NU		WARRANTY
	2	31-11-6-756-876	HEX NUT M22X1,5		WARRANTY
	2	32-21-2-282-197	NUT M12X1,5		WARRANTY
	2	31-35-1-095-452	LOCKING NUT		WARRANTY
	2	32-10-6-774-139	HEX NUT		WARRANTY
	1	21-20-7-548-804	FLY WHEEL D 220MM		WARRANTY
	-1	21-20-7-548-804	CORE RETURN		WARRANTY
				TOTAL - PARTS	0.00

JOB# 1 TOTALS
 JOB# 1 JOURNAL PREFIX 3MCS JOB# 1 TOTAL 0.00

JOB# 2 CHARGES

LABOR-----
 J# 2+95BFZZCRM MINI CAR RENTAL UNITS: TECH(S):142 WARRANTY
 COMPLAINT: MINI LOANER CAR FOR DURATION OF REPAIR WORK
 CORRECTION: LOANER CAR PROVIDED DURING REPAIRS

SUBLET	PO#	VEND INV#	INV.DATE	DESCRIPTION	WARRANTY
	8375	158789	11/19/07	LOANER DURING REPAIRS	0.00
				TOTAL - SUBLET	0.00

JOB# 2 TOTALS
 JOB# 2 JOURNAL PREFIX 3MCS JOB# 2 TOTAL 0.00

JOB# 3 CHARGES

LABOR-----
 J# 3+51BFZ100 MISC BODY EQUIP UNITS: TECH(S):142 0.00
 COMPLAINT: HOIST PAD MISSING
 CORRECTION: REPLACE RIGHT FRONT HOIST PAD WITH NEW

PARTS	QTY	FP-NUMBER	DESCRIPTION	UNIT PRICE	WARRANTY
	1	51-71-0-143-210	SUPPORT	19.10	19.10
				TOTAL - PARTS	19.10

JOB# 3 TOTALS
 PARTS 19.10
 JOB# 3 JOURNAL PREFIX 3MCS JOB# 3 TOTAL 19.10