

Sensors/Transmitters & Service Packs for Passenger Cars & Light Trucks

Application	Part No.	Torque in-lbs	Torque N.m.	Application	Part No.	Torque in-lbs	Torque N.m.
Mercury - Continued				Mitsubishi - Continued			
2004 - Continued				2010 - Continued			
Monterey Van - Continued				Lancer; Outlander			
Service Pack	20002	44	5	Sensor	28096	71	8
Mountaineer				Service Pack	20030	71	8
Sensor	●20096	44	5	2009			
Service Pack	20002	44	5	Eclipse			
2003-2002				EZ-sensor	↔33000	11.5	1.3
Mountaineer				EZ-sensor Service Pack; Alnm. Valve	34000	62	7
Sensor	●20096	44	5	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack	20002	44	5	Sensor	●20034	45-53	5-6
Mini				Service Pack	20003	45-53	5-6
2011				Galant			
Cooper				EZ-sensor	↔33000	11.5	1.3
Sensor; Includes Transmitter Only	28081	35	4	EZ-sensor Service Pack; Alnm. Valve	34000	62	7
2010				EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Cooper				Sensor; W/Alloy Wheels	●20034	45-53	5-6
Sensor; Includes Transmitter Only	28081	35	4	Sensor; W/Steel Wheels	28129	45-53	5-6
Service Pack; Does Not Include Valve ..	20023	35	4	Service Pack; W/Alloy Wheels	20003	45-53	5-6
Service Pack; W/43mm Silver Insert	20037	35	4	Service Pack; W/Steel Wheels	20010	45-53	5-6
Service Pack; W/48mm Green Insert ...	20038	35	4	Lancer; Outlander			
Service Pack; W/49mm Black Insert	20039	35	4	Sensor	28096	71	8
Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack	20030	71	8
2009-2008				Raider			
Cooper				EZ-sensor	↔33000	11.5	1.3
Sensor; Includes Transmitter Only	20083	35	4	EZ-sensor Service Pack; Alnm. Valve	34000	62	7
Service Pack; Does Not Include Valve ..	20023	35	4	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Service Pack; W/43mm Silver Insert	20037	35	4	Sensor	28154	58	6.5
Service Pack; W/48mm Green Insert ...	20038	35	4	or	28461	11.5	1.3
Service Pack; W/49mm Black Insert	20039	35	4	Service Pack; Does Not Include Stem ..	20013	58	6.5
Service Pack; W/51mm Orange Insert ..	20040	35	4	Service Pack; Includes Stem Only	20020	58	6.5
Mitsubishi				2008			
2011				Eclipse; Endeavor			
Eclipse; Endeavor				EZ-sensor	↔33000	11.5	1.3
EZ-sensor	↔33000	11.5	1.3	EZ-sensor Service Pack; Alnm. Valve	34000	62	7
EZ-sensor Service Pack; Alnm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	●20034	45-53	5-6
Sensor	20034	49	5.5	Service Pack	20003	45-53	5-6
Galant				Galant			
EZ-sensor	↔33000	11.5	1.3	EZ-sensor	↔33000	11.5	1.3
EZ-sensor Service Pack; Alnm. Valve	34000	62	7	EZ-sensor Service Pack; Alnm. Valve	34000	62	7
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
Sensor; W/Alloy Wheels	20034	49	5.5	Sensor; W/Alloy Wheels	●20034	45-53	5-6
Sensor; W/Steel Wheels	28129	45-53	5-6	Sensor; W/Steel Wheels	28129	45-53	5-6
Lancer; Outlander				Service Pack; W/Alloy Wheels	20003	45-53	5-6
Sensor; W/Alloy Wheels	20398	11.5	1.3	Service Pack; W/Steel Wheels	20010	45-53	5-6
Sensor; W/Steel Wheels	28096	71	8	Lancer; Outlander			
Service Pack; W/Steel Wheels	20030	71	8	Sensor	28096	71	8
Service Pack; W/Alloy Wheels	20008	11.5	1.3	Service Pack	20030	71	8
2010				Raider			
Eclipse; Endeavor				EZ-sensor	↔33000	11.5	1.3
EZ-sensor	↔33000	11.5	1.3	EZ-sensor Service Pack; Alnm. Valve	34000	62	7
EZ-sensor Service Pack; Alnm. Valve	34000	62	7	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	Sensor	28154	58	6.5
Sensor	●20034	45-53	5-6	or	28461	11.5	1.3
Service Pack	20003	45-53	5-6	Service Pack; Does Not Include Stem ..	20013	58	6.5
Galant				Service Pack; Includes Stem Only	20020	58	6.5
EZ-sensor	↔33000	11.5	1.3	2007			
EZ-sensor Service Pack; Alnm. Valve	34000	62	7	Eclipse			
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3	EZ-sensor	↔33000	11.5	1.3
Sensor; W/Alloy Wheels	20034	49	5.5	EZ-sensor Service Pack; Alnm. Valve	34000	62	7
Sensor; W/Steel Wheels	28129	45-53	5-6	EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3
2009				Sensor; W/Alloy Wheels	●20034	45-53	5-6
Eclipse				Sensor; W/Steel Wheels	28129	45-53	5-6
EZ-sensor	↔33000	11.5	1.3	Service Pack; W/Alloy Wheels	20003	45-53	5-6
EZ-sensor Service Pack; Alnm. Valve	34000	62	7	Service Pack; W/Steel Wheels	20010	45-53	5-6
EZ-sensor Service Pack; Rubber Valve	20008	11.5	1.3				
Sensor; W/Alloy Wheels	●20034	45-53	5-6				
Sensor; W/Steel Wheels	28129	45-53	5-6				
Service Pack; W/Alloy Wheels	20003	45-53	5-6				
Service Pack; W/Steel Wheels	20010	45-53	5-6				

● Magnet Required to Activate Sensor.
↔ Programming Tool Required.